

North America Emission Control Area Fuel Oil Non-Availability Report

ECA0100

##	1	2	3	4	5
----	---	---	---	---	---

##

##(Include Double Pound for comments, not form fields)

##Report Form ID

Ship Operator Name	Vessel Name	Flag Country	IMO ID Number
--------------------	-------------	--------------	---------------

ECA0100

Carib LPG Trading Ltd.	Aintree	PA	9175846
------------------------	---------	----	---------

6

7

8

9

Date of ECA First Notice	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry
6/10/2013	N1130 W06335	Port Moin, Costa Rica	Port Moin, Costa Rica

10

11

12

13

Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption	Number of Fuel Suppliers Contacted	Date of Entry in the ECA
NA	NA	NA	6/20/2013

14

15

16

17

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion Name of First POC

18:00

3.00

24 Corpus Christie

18

19

20

Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC? Number of fuel suppliers contacted at First POC

Y

Y

NA

21

22

23

Name of Second POC Compliant Fuel Oil at Second POC? Plan to Bunker Compliance Fuel Oil at Second POC?

NA

NA

NA

24

25

26

Number of Fuel Suppliers Contacted at the Second POC? Date of Exit from ECA? Time of Exit from ECA?

NA

6/30/2013

0:00

27

28

29

Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA
Yes		
No		

N	NA	NA
---	----	----

30

31

32

33

Previously submitted ECA0100 forms?	Number of Submitted Reports	Designated Corporate Official Name	Designated Corporate Official E-mail

Y 4 Mrs. Melissa Manning

lpg@cariblpg.com

Designated Corporate Official Phone Number	Description of Actions to Achieve Compliance
12464270867	Contacted Recope and Bunkers International in Costa Rica but there was no LSFO available there.